

	Masala Kitchen	BOQ for Masala Kitchen Cart : 6x2.550x3 (mtr.)	Lucknow	Airport	Indoor	
		Shifting & Refabrication Summary				
S.N	Particular	Description				
1	Reification Charges Cutting & Re Assembling	Refabrication of , includes cutting, welding, ms work, wall tiles Fixing, front & side , roof, ceiling changes etc.	Sqm	24	1,500	36,000
2	Material Change	Change of Lumsum Plywood FR 12mm & Laminate & ACP, re work (4 sheet Each 8x4)	Sqm	12	2,476	29,440
4	Tile	Change of Damage Tile (2 box)	Sqm	2	2,400	5,351
5	Electrical	Change of damage Electrical wire, conduit & re wiring	L/S	1	19,500	19,500
6	Solid Acrylic Surface	Change of Damage 12mm matching Corian as per required	Sqm	1	14,800	14,800
7	Paint	Re paint on poles & façade misc.	Sqm	3	2,400	7,200
8	Dismantling & Shifting Labour	Dismantling, cutting & shifting, Transportation, from Departure to Arrival New Location	L/S	1	18,000	18,000
	TOTAL					1,30,291
	Note	GST Extra If any major change and material damage occurs during shifting, will be discussed and valuated separately				