

Sr. Nos.	Work description	Unit	Qty.	Supreame k. amount		Jay maa shitale amount		Jay maa shitale amount	
1	Remove 2HP 3Phase motor from duct, Rewinding, warnish and service.	Nos.	1	8500	8500	8000	8000	7800	7800
2	Labour and fitting charges	Nos.	1						
Total amount				8500		8000		7800	

L1