

	Reliable Engg					
Item	Qty	Rate	Amt	10 % Disc	Rate 1	Amt 1
Entrance door front left side bottom fully rusted, need to replace the rusted square tube and sheet	1	7500	7500	750	6750	6750
Entrance Right side door mini door modification and bottom rusted sheet to be replaced - 1job	1	13800	13800	1380	12420	12420
Freight	1	1000	1000	100	900	900
Total			22300			20070