

Ramendra Singh

From: Naseer Shaikh
Sent: 19 August 2024 13:33
To: Ramendra Singh
Cc: Lovejot Sekhon Kcorp; Shashikant Vishwakarma
Subject: RE: Reason for all parts
Attachments: 2024_08_09 5_33 pm Office Lens (1).pdf; 2024_08_09 5_33 pm Office Lens.pdf; 2024_08_09 5_32 pm Office Lens.pdf

Dear Ramendra,

Please review the updates on the following points, along with the attached service report copies for your reference.

Item	Qty	Rational combi Location	Remark
Emptying pump SCC	1	Domestic lounge	Worn-out drain pump components can occur when the oven is used continuously
Air inlet filter cpl. SCC_WE, CM_P 61-202	1	International Lounge L 3 (West side)	The air filter should be replaced every 6 months, or as needed based on the oven's usage, to prevent breakdowns
GEO SCALE R 5 LTR	1	Cleaning chemical (used for all ovens)	Chemical used for all rational oven cleaning
GEO SCALE R 5 LTR	1	Cleaning chemical (used for all ovens)	Chemical used for all rational oven cleaning
Control pcb *Energy opt* CM_P 623-202; LM2; A	1	International Lounge (east lounge)	PCB failure occurred due to internal transformer malfunction, resulting in overheating, solder joint failure, and electrical shorts. As a result, the PCB is beyond repair and needs to be replaced
Sealing f. panel insert SCC_WE, CM_P	1	International Lounge (east lounge)	The electronic panel's door gasket, which prevents moisture from reaching the PCB, is worn out and needs replacement
Dial SCC line CM 61-202	1	International Lounge (east lounge)	Touch panel screen guard damaged/worn out, replacing recommended
Cap for service door C-/CPC-/SCC-Line, 61-202	1	International Lounge (east lounge)	Door handle screw cap
Meat probe sensor CM_P 61-102	1	International Lounge (east lounge)	The meat probe, used to check the internal food temperature in the oven, is completely worn out due to continuous use.

Thanks & Regards
Naseer Shaikh
Maintenance Manager
Mob No: +91 9833561007
Email Id: naseer.shaikh@mumbailounge.in



From: Ramendra Singh <ramendra.singh@semolinakitchens.com>
Sent: 19 August 2024 11:35
To: Naseer Shaikh <Naseer.shaikh@mumbailounge.in>
Cc: Lovejot Sekhon Kcorp <lovejot.sekhon@k-corp.in>; Shashikant Vishwakarma <shashikant.vishwakarma@k-corp.in>
Subject: Reason for all parts

Dear Naseer,

Could you please explain why so many parts are needed all at once?

Item	Qty
Emptying pump SCC	1
Air inlet filter cpl. SCC_WE, CM_P 61-202	1
GEO SCALE R 5 LTR	1
GEO SCALE R 5 LTR	1
Control pcb *Energy opt* CM_P 623-202; LM2; A	1
Sealing f. panel insert SCC_WE, CM_P	1
Dial SCC line CM 61-202	1
Cap for service door C-/CPC-/SCC-Line, 61-202	1
Meat probe sensor CM_P 61-102	1

Thanks & Regards,
Ramendra Singh
9999118677