

## **CONQUER COOL BREEZE**

Authorised Sales & Service Dealer for BLUE STAR #216/2,Plot No.3, Nagawarapalya C.V. Raman Nagar Post Bangalore - 560093

## BOQ No: CCB/R/FEB/24/1405 R1

To,

## BLR LOUNGE SERVICES PVT. LTD

Kempegowda International Airport, KIAL Rd Devanahalli, Bengaluru (Bangalore) Urban,Karnataka, 560300

Kind Att :- Nashid Ahamad

## SUB: Quotation for DX Unit Coil replacement work

Thank you very much for inviting us to quote for the subject job. Based on the discussions had with you, we are pleased to submit our offer as under.

BOQ for Supply						
Sl.no	Item Description	SAC	QTY	UOM	Rate	Amount
1	Supply of DX Unit Coil 42"X36.5"3Rows 3/8	74091100	1	Nos	45500	45,50
2	Labour Charges for Old Coil Dismantling and New Coil Installaition	995463	1	Nos	5500	5,50
	Ductable unit rectification : Referigerant leak arresting at DX coil, filter drier replacement,					
3	Nitrogen pressure testing, 11 Kgs of refrigerant charge , testing , commissioning and one	995463	1	Nos	35000	35,00
	time unit service.					
4	Transportation	995463	1	Nos	1875	1,87
				•		87,87
	Total Cost excluding tax					87,87
	Tax Grand Total					15,81 103,69
-	ment : 100% Advance against PO very : 1-2 week					
	o : 29AGFPR8094Q1Z6 o : AGFPR8094Q					
	NQUER COOL BREEZE					
Amit k	umar					

Mob no :+91 9686191042



Date : 13.02.2024