

## Smrutika Thoti

---

**From:** Shadab Sukri  
**Sent:** 29 May 2024 15:54  
**To:** Smrutika Thoti  
**Cc:** Dev.Joel@gmrgroup.in; Shahbaaz Ahmad Husain  
**Subject:** FW: Replacing Flex - GHL - HYD outlets

Dear Smrutika,

Please upload PR urgently

Specification – Supply & installation Printed Flex on existing barricade (Art Work will provide by GHL )

S no	Outlet	Length in Mt.	Height in Mt.	Quantity Sq. Mt.
<b>ISHA:</b>				
1	FF – 14 – Haati Kaapi – Bulk Head	2.1	2.2	4.62
		8.5	5.2	44.2
2	FF 17 – Dhaba 1986	34	5.2	176.8
3	FF -18 Carls Jr	34	5.2	176.8
4	FF – 19 Subway	38	5.2	197.6
5	FF – 22 – D&G – Bulk Head	30	2.2	66
6	FF 25 – MC & CS	46	5.2	239.2
7	FF 27 – PH	53	5.2	275.6
8	FF -26 – Chai Point -Bulk Head	26	2.2	57.2
		4.3	5.2	22.36

Regards  
Shadab Sukri

**From:** Dev Joel <Dev.Joel@gmrgroup.in>

**Sent:** 13 April 2024 05:24 PM

**To:** Shadab Sukri <shadab.sukri@travelfoodservices.com>

**Cc:** Shahbaaz Ahmad Husain <Shahbaaz.AhmadHusain@gmrgroup.in>; Smrutika Thoti <smrutika.thoti@travelfoodservices.com>

**Subject:** RE: Replacing Flex - GHL - HYD outlets

Dear Shadab

Dimensions in requested format :

S no	Outlet	Length in Mt.	Height in Mt.	Quantity Sq. Mt.
<b><u>DSHA:</u></b>				
1	FF 46 a & b – JOP & IH	63.4	4.2	266.28
2	FF 45 a & b – MC & CS	19.5	4.2	81.9
3	FF 44 - Franks	17.25	5.2	89.7
4	Corona Bar Concept	82.4	4.2	346.08
<b><u>ISHA:</u></b>				
1	FF – 14 – Haati Kaapi – Bulk Head	2.1	2.2	4.62
		8.5	5.2	44.2
2	FF 17 – Dhaba 1986	34	5.2	176.8
3	FF -18 Carls Jr	34	5.2	176.8
4	FF – 19 Subway	38	5.2	197.6
5	FF – 22 – D&G – Bulk Head	30	2.2	66
6	FF 25 – MC & CS	46	5.2	239.2
7	FF 27 – PH	53	5.2	275.6
8	FF -26 – Chai Point -Bulk Head	26	2.2	57.2
		4.3	5.2	22.36

**From:** Shadab Sukri <[shadab.sukri@travelfoodservices.com](mailto:shadab.sukri@travelfoodservices.com)>  
**Sent:** 12 April 2024 16:59  
**To:** Dev Joel <[Dev.Joel@gmrgroup.in](mailto:Dev.Joel@gmrgroup.in)>  
**Cc:** Shahbaaz Ahmad Husain <[Shahbaaz.AhmadHusain@gmrgroup.in](mailto:Shahbaaz.AhmadHusain@gmrgroup.in)>; Smrutika Thoti <[smrutika.thoti@travelfoodservices.com](mailto:smrutika.thoti@travelfoodservices.com)>  
**Subject:** RE: Replacing Flex - GHL - HYD outlets

**\*\* EXTERNAL EMAIL - Please verify the sender before taking any action, replying , clicking any links or opening attachments \*\***

Dear Dev,  
Please share in below format to upload

Sr.No	Outlet	Length in Mt.	Height in Mt.	Quantity Sq. Mt.
1	FF 46 a & b – JOP & IH	21.75	4.3	93.52

Regards  
Shadab Sukri

**From:** Dev Joel <[Dev.Joel@gmrgroup.in](mailto:Dev.Joel@gmrgroup.in)>  
**Sent:** 12 April 2024 04:09 PM  
**To:** Shadab Sukri <[shadab.sukri@travelfoodservices.com](mailto:shadab.sukri@travelfoodservices.com)>  
**Cc:** Shahbaaz Ahmad Husain <[Shahbaaz.AhmadHusain@gmrgroup.in](mailto:Shahbaaz.AhmadHusain@gmrgroup.in)>  
**Subject:** Replacing Flex - GHL - HYD outlets

**CAUTION:** This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear Shadab,

We have to replace below outlets flex and please ask our team to raise request in safal.  
These amounts except Corona bar will be deduct from GHIAL Invoice.

**DSHA : Ht : 4.3 mtr**

FF 46 a & b – JOP & IH ---- 21.75x 19.5 x 21.25 mtr -  
FF 45 a & b – MC & CS ---- 9.75 x 7.5 mtr  
FF 44 - Franks ---- 2.25 x 17.25 x 075  
Corona Bar Concept

**ISHA :**

FF – 14 – Haati Kaapi – Bulk Head – 2.1 mtr x 2.2 mtr Ht. + 8.5 mtr x 5.2 mtr  
FF 17 – Dhaba 1986 – 34 mtr x 5.2 mtr Ht  
FF -18 Carls Jr – 34 mtr x 5.2 mtr Ht  
FF – 19 Subway – 38 mtr x 5.2 mtr  
FF – 22 – D&G – Bulk Head – 30mtr x 2.2 mtr  
FF 25 – MC & CS – 46 mtr x 5.2 mtr  
FF 27 – PH – 53 mtr x 5.2 mtr  
FF -26 – Chai Point --- 26 mtr x 2.2 mtr(Bulk Head) + 4.3 mtr x 5.2 mtr

Regards,  
DJ

---

This e-mail contains information which is confidential and/or legally privileged. If you are not the intended recipient , you are hereby notified that any disclosure, copying, distribution or the taking of any action in reliance on the contents of this e-mail is strictly prohibited. If you have received this e-mail in error, please destroy it and notify us by reply e-mail or by telephone. Internet E-mail messages may be subject to delays, non-delivery and unauthorised alterations and we shall not be responsible for the consequence(s) in such event(s). All reasonable precautions have been taken to ensure no viruses are present in this E-mail. We cannot accept responsibility for loss or damage arising from the use of this E-mail or attachments and recommend that you subject these to your virus checking procedures prior to use.