

## Ramendra Singh

---

**From:** Rupesh Kumar  
**Sent:** 30 October 2024 13:15  
**To:** Ramendra Singh  
**Subject:** Fw: REGARDING MERRY CHEF COMPLAINT AT SUBWAY KOLKATA AIRPORT  
**Attachments:** SUBWAY AIRPORT KOLKATA (E4S 90001).pdf

JFYI.....

---

**From:** Rahul Singh <rahul.singh@acetechnologiesgroup.com>  
**Sent:** 10 October 2024 00:32  
**To:** Kolkata Subway <subway.kolkata@travelfoodservices.com>  
**Cc:** Brands Kolkata <brandskolkata@travelfoodservices.onmicrosoft.com>; ANIMESH SARKAR <animesh.sarkar@travelfoodservices.com>; Rupesh Kumar <rupesh.kumar@travelfoodservices.com>; Poonam Chauhan <service.north@acetechnologiesgroup.com>; Mohan Singh <service.delhi@acetechnologiesgroup.com>; Yogesh Khitoliya <service.north1@acetechnologiesgroup.com>; Sanjay Mohite <sanjay.mohite@acetechnologiesgroup.com>  
**Subject:** RE: REGARDING MERRY CHEF COMPLAINT AT SUBWAY KOLKATA AIRPORT

**CAUTION:** This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear Sir,

Greetings from ACE Technologies!!

Sorry for late revert as I was on leave.

Our engineer visited at your store to make the unit up and replaced all the component except door seal (because wrong one delivered). During repairing of machine we got display defective. Please get the fault founding in details.

When engineer done all the activity and also achieved the preheat temp. once. We did the recomissioning test successfully after cool down the machine and again put the machine to achieve the preheat temp. Display suddenly blanked when machine was on 160 degree temp.

So it need to replace to make unit functional further. Please get the quote below for required spare part...

SR. NO.	Item Code	Item Description	HSN CODE	QTY	Unit Rate INR	Unit Amount	Disc %	Disc Amount	Total INR
1	30Z0503	SWITCH ON/OFF ROCKER DPS	0	1	6565.00	6565.00	0%	0.00	6565.0
2	P30Z5009	TOUCH SCREEN & PCB ASSY (e5)	0	1	83120.13	83120.13	0%	0.00	83120.1
3									
						<b>Sub Total</b>			89685.1
						<b>Freight Charge</b>			350.0
						<b>DL GST @ 18% TRD</b>			16206.3
						<b>DL CGST @ 9% TRD</b>			0.0
						<b>DL SGST @ 9% TRD</b>			0.0
						<b>Total</b>		<b>INR</b>	<b>106241.4</b>
<b>Amount Payable (In Words) :</b>		<b>Rupees One Lakh Six Thousand Two Hundred FourtyOne Paise FourtyFive Only</b>							

Excuse my typo.

With Best Regards,  
Rahul Singh

**ACE** Technologies

503,Crown Height Sector-10,Rohini,New Delhi-110085

Near Rithala Metro Station

Land Line No.011-45874299, Mob. 7506391152

Fax No. 22-28704108

Email Id : [rahul.singh@acetechnologiesgroup.com](mailto:rahul.singh@acetechnologiesgroup.com)

Website : <http://www.ace-technologiesgroup.com>

Connect with us on [Facebook](#), [LinkedIn](#), [Twitter](#) & [YouTube](#)