## Sowri Raja

From:

Karthick K

Sent:

09 September 2024 11:57

To:

Sowri Raja

Subject:

RE: Need Approval to raise new PR

Please proceed..

Regards, Karthick

From: Sowri Raja <sowriraja.m@travelfoodservices.com>

Sent: 09 September 2024 11:57

To: Karthick K < karthick.k@travelfoodservices.com>

Subject: Need Approval to raise new PR

Dear Sir

Please find below trail mail, quotation for cashier room 1.0 Tr non inverter AC unit quotation,

Earlier we got quotations for 1.8TR AC unit, Total Cost Rs 66826/- + GST 28% and 18% 1.0 TR AC unit Total Cost Rs 57840/- + GST 28% & 18%

Kindly advise/approval to raise new PR for the same.

Regards, Sowri Raja Travel Food Services chennai Pvt. Ltd.

From: Service AppleAirSystem < service@appleairsystem.com>

Sent: 09 September 2024 11:46

To: Vijayakumar S < vijayakumar.s@k-corp.in >; Sowri Raja < sowriraja.m@travelfoodservices.com >

Cc: Bala annamalai < bala@appleairsystem.com >

Subject: Re: SPLIT AC BOQ

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Dear Sir,

Kindly check the below mentioned split ac boq.

	Daikin Split Ac BOQ for the Equipments -Non Inverter	البد	Unit	Rate	Amount
No.	Description	1	Nos	26172	26172
1	1.0 TR Daikin Non inverter Split AC with cordless remote	•	,100		26172
	Total Total				7328
	Gst @ 28%				
	Grand total for units withtax				33500
il No.	Description	Qty	Unit	Rate	Amount
1	Refrigerant Piping				
	Refrigerant Pine made of copper pipe with fitting of following sizes for all unit				
	Split Ac consisting of indoor units and out door units - Soft Drawn .8" G	15	Rmt	950	14250
	Suction Line & Liquid line	15	KIIR	930	14200
	Electrical Cabling	1 4 5	Rmt	110	1650
2	4 core 1.5 sq.mm Communication Cabling between indoor and outdoor	15	-		1000
3	3 core 2.5 sq.mm Communication Cabling between indoor and outdoor-Power Cable	Ro	Rmt	140	<u> </u>
	Drain Pipe	<u> </u>	<del>  </del>		4000
4	PVC Drain Pipe With Insulation	6	Rmt	320	1920
5	Additional Drain Pump	1	Rmt	5500	5500
	Supports				<del> </del>
6	Anti Vibration Mountings Pads	1	Nos	50	50
	Outdoor Split ac stand	1	Nos	850	850
7	Hitech supports for the refrigerant pipes and drain pipes	Ro	Nos	280	
8		1.5	Kg	1100	1650
9	Supply of Gas Supply of N2 Cylinder	1	Lot	1000	1000

Total				26870
Gst @ 18%				4837
Grand total for units withtax				31707
1 Installations of the units	1	Nos	1500	1500
Installation Of Daikin Non inverter Split	10	Rmt	180	1800
2 Towards Labour charges for Additional Copper Pipe Laying Work	1	Lot	1500	1500
3 Transportation Charges Total				4800
Gst @ 18%				864
Grand total for units withtax				5664
Grand total for (A+B+C)	and the state of the state of			70871
Note: The quantities given above are tentative. The actual depends on complet	tion of Projects			
Also Other Material quantities depends on project completion				

On Tue, Sep 3, 2024 at 12:40 PM Service AppleAirSystem < service@appleairsystem.com > wrote:

Dear Sir,

Kindly check the below mentioned split ac boq.

	Daikin Split Ac BOQ for the Equipments -Non Inverter  Description	Qtv	Unit	Rate	Amount
SI No.		1	Nos	35156	35156
1	1.8 TR Daikin Non inverter Split AC with cordless remote				35156
	Total Total				
	Gst @ 28%				9844
	Grand total for units withtax				45000
SI No.	Description Description	Qty	Unit	Rate	Amoun'
1	Refrigerant Piping	-		1 1	
	Refrigerant Pipe made of copper pipe with fitting of following sizes for all unit				<b></b>
	Split Ac consisting of indoor units and out door units - Soft Drawn .8" G		<u> </u>		
	Suction Line & Liquid line	15	Rmt	950	14250
	Electrical Cabling			1	1