

Rujo Engineering Private Limited

#1375, TNHB Main Road, Velachery
Chennai Tamil Nadu 600042
India
info@rujoengg.com
7824848440
GSTIN 33AAICR0479B1ZN

ORIGINAL

TAX INVOICE

Invoice No	: RE/GST/24-25/077	Place Of Supply	: Tamil Nadu (33)
Invoice Date	: 11/11/2024		
Terms	: Net 15		
Due Date	: 26/11/2024		
WO.#	: TFSCPL/AMC/2023-24/16		

Bill To	Ship To
Travel Food Services Private Limited Central Kitchen, Next to S2 Police Station, Chennai International Airport, Chennai, 600027 Tamil Nadu India GSTIN 33AADCB2762L1ZP	Central Kitchen, Next to S2 Police Station, Chennai International Airport, Chennai, 600027 Tamil Nadu India

#	Item & Description	HSN /SAC	Qty	Rate	CGST		SGST		Amount
					%	Amt	%	Amt	
1	Annual Maintenance Contract 2nd Service Location : Travel Food Services Pvt. Ltd Cleaning of Hood, Horizontal & Vertical Duct, Blowers 1. Main Kitchen	9954	1.00 Nos	1,18,550.0 0	9%	10,669.50	9%	10,669.50	1,18,550.00

Total In Words
Rupees One Lakh Thirty-Nine Thousand Eight Hundred Eighty-Nine Only

Notes

Thank you for the payment. You just made our day.

Bank Name :City Union Bank
 A/C No :510909010111563
 IFSC :CIUB0000262
 Branch :Velachery

Terms & Conditions
 This is automated Invoice, signature not required

Sub Total	1,18,550.00
CGST9 (9%)	10,669.50
SGST9 (9%)	10,669.50
Total	₹1,39,889.00
Balance Due	₹1,39,889.00



Authorized Signature

Main kitchen :

Kitchen exhaust units - second half yearly cleaning charge
 → opex cost
 → Attached AMC Agreements
 → Recommended for payments
 → Bill received on 19/11/2024.

(Signature)
 M. SOWRI RAJA
 19/11





Ref. No. TFSCPL/AMC/2023-24/16

Date: 30th October 2023

ANNUAL MAINTENANCE CONTRACT AGREEMENT

This agreement is executed at Chennai on this day 30th of October 2023, between RUJO ENGINEERING PRIVATE LIMITED, No: 1375, TNHB Main Road, Velachery, Chennai – 600042.

AND

Travel Food Services Chennai Pvt. Ltd., Near S2 Airport Police Station, International Terminal, Chennai Airport, Chennai – 600027, GSTIN – 33AAECT8192M1ZS for a period from

Contract Tenure:

This tenure is effective from 01-11-2023 to 31-10-2024 for a period of 12 months. We also reserve right to terminate or extend the contract any time with or without assigning reason.

SCOPE OF WORK

Job Involved:


- Robotic Kitchen Duct Cleaning

Place of Service:

- Travel Food Services Chennai Pvt. Ltd. (TFSCPL), Chennai International Airport

Commercial Terms:

The following rates will be applicable for a period of One year as per the attached Annexure.



Travel Food Services Chennai Private Limited

Registered Office: Block-A, South Wing, 1st Floor, Shiv Sagar Estate, Dr. Annie Besant Road, Worli, Mumbai, MH 400018 India

T: (+91-22) 4322 4322 | E-mail: info@tavefoodservices.com | Website: www.tavefoodservices.com

CIN U55101MH20137PTC249980

Handwritten signatures:
M. S. Srinivasan
M. S. Srinivasan



Handwritten signature:





Annexure

Sl.No.	Item & Description	HSN /SAC	UOM	Qty.	Rate	Amount
1	Robotic Kitchen Cleaning - Annual Maintenance Contract Yearly Twice Location : DOMESTIC TERMINAL Cleaning of Hood, Horizontal & Vertical Duct, Blowers 1. LOUNGE-B 2. COPPER CHIMNEY 3. DOMESTIC CURRY KITCHEN 4. TRAVEL CLUB A LOUNGE 5. IRIS HOUSE KITCHEN 6. KFC 7. PIZZA HUT	9954	Nos	2	136541.67	273083.33
2	Robotic Kitchen Cleaning - Annual Maintenance Contract Yearly Twice Location : INTERNATIONAL TERMINAL Cleaning of Hood, Horizontal & Vertical Duct, Blowers 1. INTERNATIONAL CURRY KITCHEN 2. NEW LOUNGE 3. NEW LOUNGE & BAR	9954	Nos	2	45458.33	90916.67
3	Robotic Kitchen Cleaning - Annual Maintenance Contract Yearly Twice Location : Travel Food Services Chennai Pvt. Ltd Cleaning of Hood, Horizontal & Vertical Duct, Blowers 1. Main Kitchen	9954	Nos	2	118550.00	237100.00
Total						6,01,100.00
CGST 9%						54,099.00
SGST 9%						54,099.00
Grand Total						7,09,298.00








Travel Food Services Chennai Private Limited

Registered Office: Block-A, South Wing, 1st Floor, Shiv Sagar Estate, Dr. Annie Besant Road, Worli, Mumbai, MH 400018 India

T: (+91-22) 4322 4322 | E-mail: info@tavefoodservices.com | Website: www.travelfoodservices.com

CIN U55101MH2013PTC249980



General Condition:

Limitation of Liability:

In no event we will be liable for any consequential loss whatsoever direct or indirect arising out of damage caused by fire, rain, storm, theft, etc.

Termination:

Either party may terminate the agreement at any time by giving (1) month notice to the other party or the contractor shall refund the proportionate balance amount out of the total amount paid to them by TFSKPL for the unexpired period out of the total period for which agreement is executed.

Notice:

All the notice and other communications hereunder shall be in writing, except as herein specifically provided, and shall be deemed to have been given when mailed by registered mail, to the intended recipient thereof at its address shown herein above or to such other address as the intended recipient may specify in a notice pursuant to this section.

Arbitration:

All disputes & differences arising out of connected with this contract falling amicable settlement will be referred to a mutually approved arbitrator, Chennai.

IN WITNESS WHEREOF, the parties have hereunto set their respective hands these presents on the day, month and year first above written.


Signed Sealed and Delivered by

Signed Sealed and Delivered by

Travel Food Services Chennai Pvt Ltd
Through its Authorized Signatory



Rujo Engineering Pvt. Ltd.
Through its Authorized Signatory




Travel Food Services Chennai Private Limited

Registered Office: Block-A, South Wing, 1st Floor, Shiv Sagar Estate, Dr. Annie Besant Road, Worli, Mumbai, MH 400018 India

T: (+91-22) 4322 4322 | E-mail: info@tavefoodservices.com | Website: www.travelfoodservices.com

CIN U55101MH20137PTC249980





KITCHEN DUCT CLEANING REPORT

Client Details



Travel Food Services Chennai Pvt.Ltd
Next to S2 Airport Police Station,
Chennai International Airport, Chennai 600027

Date of Work	28.10.2024 TO 30.10.2024 & 07.11.2024
Total no. of days	4 Days

Service Provider

RUJO ENGINEERING PRIVATE LIMITED.

No: 1375, TNHB Main Road,






Velachery, Chennai - 600 042.

Tel: 044 - 42117000 | Mob:7824848440


Email: info@rujoengg.com

Web: www.rujoengineering.com

Equipment we use during duct cleaning process:



Contents



1. Site Description

Travel Food Services Chennai Pvt.Ltd
Next to S2 Airport Police Station,
Chennai International Airport, Chennai 600027

2. Floor Summary

System Name

- Department - kitchen

Location

- kitchen Hood Exhaust Blower
- Horizontal & Vertical Duct

System Type

- Kitchen Exhaust

3. Summary of work

- Before the cleaning process, Duct inspection is conducted using Robot truck inside the supply duct.
- Cleaning brushes depend on the size of duct & dust inside the duct.
- Air hose for the negative air unit is properly fixed in the duct system.
- Duct cleaning is being done using Lifa Air brushing machine.
- Dust is collected to the negative air unit through the hose while brushing.
- Duct inspection is conducted using Robot truck as post visual inspection to ensure the cleaning level.
- Pre- & post inspection and cleaning process are being recorded for submission.
- Entire Kitchen exhaust duct unit is being cleaned segment wise repeating the above-mentioned processes.

4. Kitchen Cleaning Report with Photographic Evidence

WORK LOCATION

Main Kitchen Area



NO. OF PERSONS WORKED

5



Before Cleaning

After Cleaning




HOOD 1






HOOD 2




Before Cleaning



After Cleaning





Before Cleaning





After cleaning




Hood 2 Horizontal Duct



Hood 2 Vertical Duct






Hood 2 Blower Before Cleaning




After Cleaning




HOOD 3




Before Cleaning




After Cleaning





Hood 3 Vertical Duct Before Cleaning




After Cleaning




Hood 3 Horizontal Duct






Hood 3 Blower Before Cleaning





After Cleaning





Hood 4 Grill




Before Cleaning



After Cleaning






Before Cleaning






After Cleaning





Hood 4 Without Grill




Before Cleaning




After Cleaning




Before cleaned grills





After cleaned grills




Hood 4 Horizontal duct



Hood 4 Vertical Duct





Hood 4 Blower Before cleaning





After cleaning




Bakery hood



Working Photos:



Observation Photos on Duct Cleaning Process:



Observation:

- High Level of Oil, Grease and Dust particles accumulated inside the ducts, hoods, and exhaust blower of the kitchen.

Conclusion:

- All kitchen exhaust ducts & blower were satisfactorily cleaned.
- The duct cleaning works were verified by post-visual inspection.
- The kitchen exhaust cleaning works were also validated by using photographic before and after.
- The results are shown on pages 4 to 15 which illustrates satisfactory cleaning levels.
- We suggest cleaning on a 6-month basis to avoid heavy grease and oil.

Service Provider:

For Rujo Engineering Private Limited

Company Name:

Travel Food Services Chennai Pvt.Ltd

Signature with Seal

Accepted By: Signature with Seal

