

Service Report

Compliant No:

Report No: **15291**
Service Provider:

Customer: Subhley
Date: 28/7/24
Time In: 11:30 AM Time Out: 5:00 PM
Nature of Call: Installation BD PM Inspection Visit
Type of Service: Warranty Chargeable Courtesy Call
Contact Person: Biju Singh Brand: Merrychef
Tel No: 8013701031 Model: eyst30sgcuiswteu Serial No: 170721309000
Customer Compliant

Service Rendered: visit on stor. and check machine. Required. ~~speed~~ motor speed controller board, left side. Magma from left. Sealer. Motor. 3. Dor. Gasket. ~~also~~ Abtor replacement. Inspect the. Machine again
Material Required / Used: Additional Requirement

Line Voltage: _____ PH-E: _____ N-E: _____
Physical Condition of Machine: All accessories connection OK
Temperature of the unit: _____ C Ambient Temperature: _____ C

Condensor: Motor HP: _____ Inlet Water Temp: _____ C Outlet/Rinse Wash Water Temp: _____ C
Mix Temp (Fresh): _____ C Final Product Inlet Air Temp: _____ C
Temp : _____ C Cycle Time Mins: _____

Customer Remarks:

Name - Signature & Company Stamp/ Mobile No. Of the Customer: Suvil Singh 28/7/24
Name & Signature of the Engineer: [Signature] 28/7/24